



# SAFE-LOC CONNECTOR

## EXTERNAL GAS CONNECTION

FOR USE ON CK9, 17, 130, 150, FL130, FL150, MR70



## SL2-35

TYPICAL GAS HOSE CONNECTION 3/8"-24 tpi Male  
(THIS DOES NOT COME WITH SL2-35)



EXISTING POWER CABLE FROM THE TIG TORCH. IT CAN BE RED OR BLACK WITH A 3/8" DIAMETER EXTERNAL THREAD ON THE END



6 FOOT GAS HOSE

"B" FITTING EXTERNAL GAS CONNECTION TO  
SUPPLY ARGON TO THE TIG TORCH

AW-430 "B" COUPLING IF REQUIRED



DINSE 35  
(1/2" 12.8mm)

THE SL2-35 IS AN EXTERNAL GAS AND POWER CABLE CONNECTOR.

***YOU NEED TO KNOW HOW THE GAS IS GOING TO GET TO THE TIG TORCH.***

- DOES IT COME FROM THE REGULATOR TO THE TIG TORCH
- IS THERE A FEMALE THREADED CONNECTION ON THE WELDING MACHINE TO CONNECT THE SL2 "B" FITTING INTO
- THE SL2 ARGON HOSE IS 6 FEET LONG. IF YOUR GAS REGULATOR OR GAS SUPPLY TO THE TIG TORCH IS FURTHER, YOU MAY NEED A COUPLING AND ALSO A GAS HOSE EXTENSION