




SAFE-LOC CONNECTOR



GAS FLOW-THRU ONLY

FOR USE ON CK9, 17, 130, 150, FL130, FL150, MR70

SL2-35M



THE SL2-35M IS A GAS FLOW-THRU CONNECTOR.
YOU NEED TO KNOW HOW THE GAS IS GOING TO GET TO THE TIG TORCH.

- DOES YOUR MACHINE HAVE A SOLENOID AND A FLOW-THRU CONNECTION AT THE POWER CONNECTION